

Chassell Township 5-year Road Repair Plan

5A Plan		
Road	Rating	Explanation
Boundary	2	this rating pertains to the eastern most end and there are some 1 ratings within this area
Boundary	2	this rating pertains to the area between the easternmost end and what the township had paved; some spots in this stretch merit a 1 rating
Boundary	6	this rating pertains to the area that the township had paved; there are spots in this stretch that need immediate patching
Massie	1	this rating pertains to the steepest part of the road just below Lehtola Road; in addition to poor condition, the shoulder is about gone in several spots and should be barricaded to avoid potentially serious accidents
Massie	3	this rating pertains to the stretch just below Lehtola to Paradise; however, there is a lengthy stretch above Lehtola that would rate a 1. There is also a small area as you near Paradise Road that needs attention\
Creamery Rd	2	15 areas from 5-30 yards
Upper Massie	3	there seem to be a number of areas that could benefit from more gravel
North Entry 3	4	Gravel Section

5B Plan		
Road	Rating	Explanation
Portage Entry	3	Longitudinal cracking and minor spalling in need of crack repair
Creamery Rd	2	15 areas from 5-30 yards
Massie	3	this rating pertains to the stretch just below Lehtola to Paradise; however, there is a lengthy stretch above Lehtola that would rate a 1. There is also a small area as you near Paradise Road that needs attention\
North Entry 2	3	significant spalling in one location just past curve, alligator cracking
2nd Street	6	Longitudinal and transverse cracks - slight raveling
3rd Street	6	longitudinal and transverse cracks - slight raveling depression at US 41 Intersection
4th Street	6	Slight Longitudinal and Transverse Cracks Rutting Pothole
5th & 1/2 Street	3	Severe Open Raveled Alligator Cracking
6th Street	4	Severe Longitudinal and Transverse Cracks - Alligator Cracking - Potholes
7th Street	4	Severe Raveling and Patches
N. Hamar Street	3	Patching - Open Raveled Alligator Cracking - Potholes
S. Hancock Street North of 6th	4	Severe Longitudinal and Transverse Cracks - Alligator Cracking - Potholes
Old U.S. 41 to Last Resident	5	Transverse Cracks - Heave from culvert
Old U.S. 41 to Past Last Resident	1	Dead End - Road closed at bridge
Lower Pike Rd	4	Exposed culvert at the S end of the road
Klingville	3	alligator cracking, small sections of significant wear/potholes
Klingville extension	1	culvert exposed and cracked at south end

Chassell Township Road Committee Condition Ratings

September 2018

Brian Waters, Keith Meyers, Steve Spahn, Dale Peterson, Ericka Malone

STREET	GRADE	CONDITION
Old U.S. 41 to Past Last Resident	1	Dead End - Road closed at bridge
Massie	1	this rating pertains to the steepest part of the road just below Lehtola Road; in addition to poor condition, the shoulder is about gone in several spots and should be barricaded to avoid potentially serious accidents
Klingville extension	1	culvert exposed and cracked at south end
Boundary	2	this rating pertains to the eastern most end and there are some 1 ratings within this area
Boundary	2	this rating pertains to the area between the easternmost end and what the township had paved; some spots in this stretch merit a 1 rating
Creamery Rd	2	15 areas from 5-30 yards
5th & 1/2 Street	3	Severe Open Raveled Alligator Cracking
N. Hamar Street	3	Patching - Open Raveled Alligator Cracking - Potholes
Lehtola	3	there are some areas that appear to need more gravel
Massie	3	this rating pertains to the stretch just below Lehtola to Paradise; however, there is a lengthy stretch above Lehtola that would rate a 1. There is also a small area as you near Paradise Road that needs attention
Upper Massie	3	there seem to be a number of areas that could benefit from more gravel
North Entry 2	3	significant spalling in one location just past curve, alligator cracking
Portage Entry	3	Longitudinal cracking and minor spalling in need of crack repair
Klingville	3	alligator cracking, small sections of significant wear/potholes
Old Timer	3	minor washboarding, width reduction on West end
Tapio	3	washboard, good base
Klingville extension	3	culvert exposed and cracked at south end
6th Street	4	Severe Longitudinal and Transverse Cracks - Alligator Cracking - Potholes
7th Street	4	Severe Raveling and Patches
S. Hancock Street North of 6th	4	Severe Longitudinal and Transverse Cracks - Alligator Cracking - Potholes
Worham - Gravel	4	A few parts may be a 3, but greater than 99% is a solid 4.
Jalkanen - Gravel	4	Road is in great shape now, but for a month or so in the spring this road is a negative 4!
Cote - Gravel	4	I did not drive down this, just looked, but it is in good shape. Just a single lane gravel road. This road is like the Jalkanen, a 4 now but can be in bad shape for a month in the spring. There is a short, 1/4 mile section that is paved as you go toward the Chassell-Painesdale road, and I would give that part a 5. Very similar to the paved parts of the Worham.
Fishes - Mostly Gravel	4	
Mailman	4	
Monette	4	
North Entry 3	4	
Sturgeon River Rd	4	
Lower Pike Rd	4	
Creamery Rd	4	
Routsi	4	narrows at end of 2 track
Virenius	4	narrow
South Entry Gravel	4	
Channel View Lane	4	
Old U.S. 41 to Last Resident	5	Transverse Cracks - Heave from culvert
Worham - Paved	5	If we made Creamery a 4, this is a five. There are a lot of lateral cracks and some longitudinal cracks, and the raveling is there. But the road is nice to drive on, smooth.
North Entry 1	5	Evenly spaced transverse cracks
Klingville S Segment	5	newer than other section, minor cracking
2nd Street	6	Longitudinal and transverse cracks - slight raveling
3rd Street	6	longitudinal and transverse cracks - slight raveling depression at US 41 Intersection
4th Street	6	Slight Longitudinal and Transverse Cracks Rutting Pothole
Paradise	6	this rating pertains to the stretch from Massie to Boundary
Boundary	6	this rating pertains to the area that the township had paved; there are spots in this stretch that need immediate patching
N. Hancock Street	7	Slight Transverse Cracks
Marinette Street	7	Slight Transverse Cracks at N. Hancock Intersection
S. Hancock Street	7	Slight Transverse Cracks
Old U.S. 41 to Pike River Road	7	Slight Transverse Cracks
Chassell-Painesdale	7	this rating pertains to the area west of the Paradise Road
Paradise	7	this rating pertains to the stretch from Chassell-Painesdale to Massie
5th Street	8	Reduces to rating of 6 at U.S. 41 Intersection
S. Hamar Street	8	
Lakeshore Drive	8	may want to address ditching in a few places
Chassell-Painesdale	8	this rating pertains to the area downhill from the Paradise Road
Pike River Rd	8	
South Entry-Paved	9	